


Vehicle details

VIN	JMZKF6W76 00699766	Brand	MAZDA	Maintenance date	-
Licence Plate	TL-13-5D	Model	CX-5 2.0 SKYACTIV-G 165pk 2WD GT-Luxury	Maintenance mileage	-
Registration date	31/08/2018	Year	2018	Exterior Color	Black Metallic
Odometer	169 908 km	Engine size	1997	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	03/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Bridgestone 225/55/19 Summer 3.5 mm		Bridgestone 225/55/19 Summer 3.5 mm	
Bridgestone 225/55/19 Summer 6.5 mm		Bridgestone 225/55/19 Summer 6.5 mm	

Exterior

2



PartDoor

PositionFront left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

●●

3



PartDoor

PositionBack left

DamagesDent & Chips

SeverityDiameter (mm) > 20

Repair modeRepair

●●●●●

4



PartBumper

PositionBack

DamagesDent & Chips

SeverityDiameter (mm) > 20

Repair modeRepair

●●●●●

5



PartStep plate

PositionBack right

DamagesDent & Chips

Severity-

Repair modeFor info

●●

6



PartDoor

PositionFront right

DamagesDent & Chips

SeverityDiameter (mm) > 20

Repair modeRepair

●●●●●

7



PartBonnet

Position-

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

●●

8



PartRoof

Position-

DamagesRusty

SeverityNumber > 2

Repair modeLumpsum repair

●●●

Interior damage

1



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Smart Repair