

Vehicle details

VIN	JSAAZCA3S 00541070	Brand	SUZUKI	Maintenance date	-
Licence Plate	AM142JL	Model	SWIFT 1,2 Dualjet Hybrid Clear 61KW	Maintenance mileage	-
Registration date	27/10/2021	Year	1000	Exterior Color	White Solid
Odometer	32 274 km	Engine size	1197	interior Color	Black
Fuel	Petrol	Body Type	Saloon / Hatchback	Next technical inspection	01/10/2024
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	09/04/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓

Removable element


--	--

Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Uniroyal 175/65/15 T Winter 8.4 mm		Uniroyal 175/65/15 T Winter 8.3 mm	
Nokian 175/65/15 T Winter 7.0 mm		Nokian 175/65/15 T Winter 7.1 mm	

Exterior

1		Part	Windscreen	2		Part	Bonnet
		Position	-			Position	-
3		Damages	Stone impact	4		Damages	Dented
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Repair
3		Part	Bumper	4		Part	Door
		Position	Front			Position	Front left
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	For info

5



Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	-
Repair mode	For info

7



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

9



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

10



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

Others

11

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

12

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint