

## Vehicle details

|                   |                    |              |                                   |                           |                 |
|-------------------|--------------------|--------------|-----------------------------------|---------------------------|-----------------|
| VIN               | JSAMFH91S 00203168 | Brand        | SUZUKI                            | Maintenance date          | -               |
| Licence Plate     | K2-52-VL           | Model        | IGNIS 1.2 Smart Hybrid Comfort 5d | Maintenance mileage       | -               |
| Registration date | 16/03/2021         | Year         | 2021                              | Exterior Color            | Silver Metallic |
| Odometer          | 91 331 km          | Engine size  | 1197                              | interior Color            | Black           |
| Fuel              | Hybrid petrol      | Body Type    | -                                 | Next technical inspection | -               |
| Seats             | -                  | Transmission | Manual                            | CO2                       | -               |
| Doors             | 5                  | Gears        | 5                                 |                           |                 |

## Inspection Details

|                 |            |                 |               |
|-----------------|------------|-----------------|---------------|
| Inspection date | 16/09/2025 | Inspection loc. | Ayvens Veghel |
|-----------------|------------|-----------------|---------------|



## Generic equipment

|                         |   |
|-------------------------|---|
| Manual air-conditioning | ✓ |
| Metallic paint          | ✓ |
| Central locking         | ✓ |
| Electric windows        | ✓ |
| Park Distance Control   | ✓ |
| Audio System            | ✓ |
| Led lighting            | ✓ |

## Removable element

|                   |   |
|-------------------|---|
| Spare wheel kit   | ✓ |
| Rear parcel shelf | ✓ |

## Technical Document

|                  |   |
|------------------|---|
| User manual      | ✓ |
| Warranty booklet | ✓ |
| Key              | ✓ |
| Remote key       | ✓ |

## Tyres

|                                     |                                     |
|-------------------------------------|-------------------------------------|
| Continental 175/65/15 Summer 5.5 mm | Continental 175/65/15 Summer 6.0 mm |
| Dunlop 175/65/15 Summer 3.5 mm      | Dunlop 175/65/15 Summer 3.5 mm      |

## Exterior

|   |                                                                                      |             |                  |
|---|--------------------------------------------------------------------------------------|-------------|------------------|
| 1 |   | Part        | Bumper           |
|   |                                                                                      | Position    | Back             |
|   |                                                                                      | Damages     | Scratched        |
|   |                                                                                      | Severity    | Length (cm) > 10 |
|   |                                                                                      | Repair mode | Repair           |
| 2 |  | Part        | Bonnet           |
|   |                                                                                      | Position    | -                |
|   |                                                                                      | Damages     | Chemical deposit |
|   |                                                                                      | Severity    | -                |
|   |                                                                                      | Repair mode | Lumpsum repair   |

3



|             |                  |
|-------------|------------------|
| Part        | Bumper           |
| Position    | Front            |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

4



|             |                  |
|-------------|------------------|
| Part        | Roof post A/B/C  |
| Position    | Front left       |
| Damages     | Chemical deposit |
| Severity    | -                |
| Repair mode | Lumpsum repair   |

5



|             |                  |
|-------------|------------------|
| Part        | Door             |
| Position    | Front left       |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

6



|             |                  |
|-------------|------------------|
| Part        | Step plate       |
| Position    | Front left       |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | For info         |

11



|             |                  |
|-------------|------------------|
| Part        | Wing             |
| Position    | Back right       |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

12



|             |                  |
|-------------|------------------|
| Part        | Door             |
| Position    | Back right       |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

## Interior damage

7



●●

|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Up                       |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Replace                  |

8



●

|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Left                     |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Replace                  |

9



●

|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Right                    |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Replace                  |

10



●●●

|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Down                     |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Replace                  |