



Toyota Aygo: T867ZJ

Vinnumber:	JTDAGNAC500136050	Versionname:	Aygo X 1.0 VVT-i 53kW Play MT
First Registrationdate:	9/10/2023	Fiscalpower:	
Expertise Mileage:	54211	Power Kw:	53
Bodytype:		Body colour	Night Sky Black metallic
Gearbox:	MAN 5 VIT	Paint type	Metallic
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Petrol	Parking lot	800
Number of seats	4		
Type of rims (mounted)	Steel		
Maintenance needed	Yes		

Options

Number of keys total	1	Telephone equipment
Number keys remote	1	Luggage cover
Manual climate control		
Windows electric F		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	175 / 55 / 17 / 87 / H / Steel	4,0 mm	Goodyear	All season
	Right	175 / 55 / 17 / 87 / H / Steel	3,0 mm	Goodyear	All season
Rear	Left	175 / 55 / 17 / 87 / H / Steel	5,0 mm	Goodyear	All season
	Right	175 / 55 / 17 / 87 / H / Steel	5,0 mm	Goodyear	All season

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute

[Damage Picture - 1](#)

Ignition key, Missing, Replace



Interior, Smell, Ozone treatment



Interior, Stain, Cleaning





Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Chemical polution, Polish



Wing FR, Chemical polution, Polish



Wheel arch cover RR, Scratch(es), Replace



Fuel cap cover, Deformed / Strained, Replace and paint



Rear spoiler, Scratch(es), Repair and paint (complete)



Bumper R, Chemical polution, Polish



Roof, Chemical polution, Polish

