


Vehicle details

VIN	JTDKGNCE0 0N435026	Brand	TOYOTA	Maintenance date	-
Licence Plate	XS-04-7F	Model	Aygo 1.0 VVT-i ActieAuto x-fun APL	Maintenance mileage	-
Registration date	18/03/2019	Year	2019	Exterior Color	Red Solid
Odometer	35 140 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	25/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓



Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Continental 165/65/14 Summer 3.5 mm		Continental 165/65/14 Summer 3.5 mm	
Continental 165/65/14 Summer 6.0 mm		Continental 165/65/14 Summer 6.0 mm	

Exterior

1		Part	Door
		Position	Front left
		Damages	Dent & Chips
		Severity	Diameter (mm) > 20
		Repair mode	Repair
2		Part	Door
		Position	Back left
		Damages	Chemical deposit
		Severity	-
		Repair mode	Lumpsum repair

3



●●●

Part	Sill
Position	Left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

4



●●●

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5



●●●

Part	Sill
Position	Right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



●●

Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

8



●●●●●

Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

9



●●

Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



●●

Part	Roof post A/B/C
Position	Left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair