


Vehicle details

VIN	JTDKGNCE0 0N498546	Brand	TOYOTA	Maintenance date	-
Licence Plate	G3-18-VX	Model	Aygo 1.0 VVT-i ActieAuto 5d x-fun HPL	Maintenance mileage	-
Registration date	27/12/2019	Year	2019	Exterior Color	Red Solid
Odometer	79 243 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	13/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Hankook 165/65/14 Summer 7.0 mm		Hankook 165/65/14 Summer 7.0 mm	
Continental 165/65/14 Summer 4.0 mm		Continental 165/65/14 Summer 4.0 mm	

Exterior

2		Part	Door	4		Part	Wing
		Position	Back left			Position	Back right
		Damages	Dented			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Smart Repair

5



Part

Door

Position

Back right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Repair

6



Part

Roof

Position

-

Damages

Dent & Chips

Severity

-

Repair mode

Repair

Interior damage

1



Part

Interior cleaning

Position

Front

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

3



Part

Interior cleaning

Position

Back

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning