


Vehicle details

VIN	JTDKGN3 0N353260	Brand	TOYOTA	Maintenance date	-
Licence Plate	SR-84-2F	Model	Aygo 1.0 VVT-i ActieAuto 5d x-fun APL	Maintenance mileage	-
Registration date	01/06/2018	Year	2018	Exterior Color	Red Solid
Odometer	42 800 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	01/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓

Tyres

Continental 165/65/14 Summer 5.0 mm	Continental 165/65/14 Summer 4.5 mm
Continental 165/65/14 Summer 6.5 mm	Continental 165/65/14 Summer 6.5 mm

Exterior

1		Part	Bumper
		Position	Front right
		Damages	Scratched
		Severity	Length (cm) > 10
		Repair mode	Repair
2		Part	Door
		Position	Back right
		Damages	Dent & Chips
		Severity	Diameter (mm) > 20
		Repair mode	Repair
3		Part	Wing
		Position	Back right
		Damages	Dent & Chips
		Severity	Diameter (mm) > 20
		Repair mode	Repair
4		Part	Bumper
		Position	Back
		Damages	Scratched
		Severity	Length (cm) > 10
		Repair mode	Repair

5



●

●

●

●

Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



●

●

●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



●

●

●

●

●

Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair