


Vehicle details

VIN	JTDKGNCE5 0N648408	Brand	TOYOTA	Maintenance date	-
Licence Plate	L1-04-LH	Model	Aygo 1.0 VVT-i x-joy 5d APL	Maintenance mileage	-
Registration date	25/06/2021	Year	2021	Exterior Color	Red Solid
Odometer	38 432 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	03/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Audio System	✓



Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Hankook 165/60/15 Summer 5.0 mm		Hankook 165/60/15 Summer 5.0 mm	
Continental 165/60/15 Summer 4.0 mm		Continental 165/60/15 Summer 3.0 mm	

Exterior

1		Part	Door	3		Part	Upper tailgate / Boot
		Position	Front left			Position	-
		Damages	Chemical deposit			Damages	Chemical deposit
		Severity	-			Severity	-
		Repair mode	Lumpsum repair			Repair mode	Lumpsum repair

7



●●

Part	Wing moulding
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

8



●●●●

Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9



●●●

Part	Alloy wheel 15"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

Interior damage

2



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



Part	Fabric door lining
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Smart Repair

6



Part	Armature de dossier de siège
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Smart Repair

5



Part	Armature de dossier de siège
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Smart Repair