

Vehicle details

VIN	JTDKGNCE7 0N566938	Brand	TOYOTA	Maintenance date	-
Licence Plate	J6-73-LK	Model	Aygo 1.0 VVT-i ACTI x-fun APL 5d	Maintenance mileage	-
Registration date	09/09/2020	Year	2020	Exterior Color	White Solid
Odometer	74 814 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	10/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓



Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Hankook 165/65/14 Summer 6.0 mm		Hankook 165/65/14 Summer 6.0 mm	
Continental 165/65/14 Summer 5.0 mm		Continental 165/65/14 Summer 5.0 mm	

Exterior

2		Part	Step plate	4		Part	Wing
		Position	Front left			Position	Back left
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	Diameter (mm) > 20
		Repair mode	For info			Repair mode	Smart Repair

5



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●

6



Part	Step plate
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

●●

7



Part	Wing
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●

8



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●●

9



Part	Bonnet
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

●●●●

Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning