


Vehicle details

VIN	JTDKGNCE9 0N356647	Brand	TOYOTA	Maintenance date	-
Licence Plate	TF-42-0F	Model	Aygo 1.0 VVT-i x-fun 5d	Maintenance mileage	-
Registration date	21/08/2018	Year	2018	Exterior Color	White Solid
Odometer	49 345 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	03/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓



Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Remote key	✓
Key	✗

Tyres

Michelin 165/65/14 All seasons 4.0 mm		Michelin 165/65/14 All seasons 3.5 mm	
Vredestein 165/65/14 All seasons 6.0 mm		Vredestein 165/65/14 All seasons 5.5 mm	

Exterior

3		Part	Roof post A/B/C
		Position	Left
		Damages	Dented
		Severity	Diameter (mm) > 20
		Repair mode	Smart Repair
4		Part	Step plate
		Position	Back
		Damages	Chemical deposit
		Severity	-
		Repair mode	Lumpsum repair

5



●●●

Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

6



●●●

Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

7



●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



●●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

9



●●

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning