

Vehicle details

VIN	JTDKGNCE9 0N357507	Brand	TOYOTA	Maintenance date	-
Licence Plate	TF-41-1F	Model	Aygo 1.0 VVT-i x-fun 5d	Maintenance mileage	-
Registration date	21/08/2018	Year	2018	Exterior Color	White Solid
Odometer	24 320 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	02/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Vredestein 165/65/14 Summer 3.5 mm		Vredestein 165/65/14 Summer 5.0 mm	
Continental 165/65/14 Summer 6.0 mm		Continental 165/65/14 Summer 6.0 mm	

Exterior

1		Part	Spoiler
		Position	Front
		Damages	Broken
		Severity	-
		Repair mode	Replace
4		Part	Bumper
		Position	Back
		Damages	Scratched
		Severity	-
		Repair mode	Repair

5



Part

Wing

Position

Front right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

6



Part

Bumper

Position

Front

Damages

Scratched

Severity

-

Repair mode

Repair

●

●

●

2



Part

Fabric seat

Position

Front

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

●

●

●

3



Part

Fabric seat

Position

Back

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

●

●