

Vehicle details

VIN	JTMZ43FV6 0D088450	Brand	TOYOTA	Maintenance date	-
Licence Plate	L1-61-VF	Model	RAV4 2.0 VVT-iE 2WD Comfort 5d	Maintenance mileage	-
Registration date	16/08/2021	Year	2021	Exterior Color	Black Metallic
Odometer	62 789 km	Engine size	1987	interior Color	Blue
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	03/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Load cover	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Bridgestone 235/65/17 Summer 6.0 mm		Bridgestone 235/65/17 Summer 6.0 mm	
Bridgestone 235/65/17 Summer 7.0 mm		Bridgestone 235/65/17 Summer 6.5 mm	

Exterior

1		<table> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	2		<table> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Bumper																								
Position	Back																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
Part	Door																								
Position	Back right																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
3		<table> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Number > 2</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Dented	Severity	Number > 2	Repair mode	Smart Repair	4		<table> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Door																								
Position	Front right																								
Damages	Dented																								
Severity	Number > 2																								
Repair mode	Smart Repair																								
Part	Bumper																								
Position	Front																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
5		<table> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	6		<table> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Bonnet																								
Position	-																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Roof																								
Position	-																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
7		<table> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>Number > 2</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Wing	Position	Back left	Damages	Dent & Chips	Severity	Number > 2	Repair mode	Repair													
Part	Wing																								
Position	Back left																								
Damages	Dent & Chips																								
Severity	Number > 2																								
Repair mode	Repair																								