



TOYOTA Rav4 2010 Crosssport Diesel

rav4 2.2 d-4d 2wd 150cv

VIN NO JTMZC31V40D011361
Registration Number EL487HS



MOT Date

2023-11-15

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2011-11-30

Odometer Reading



174861 km

Country First Registered



Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002152010
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	
Colour	Black	Engine Size (cc)	2231
Engine Size	2.2	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	159

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Cruise control	Tyre Mobility Kit	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Trip Computer	Stability control


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	KLEBER KLEBER-QUADRAXER 2 SUV	225/65//R17 - 102H / 2 mm
	KLEBER KLEBER-QUADRAXER 2 SUV	225/65//R17 - 102H / 2 mm
	KLEBER KLEBER-QUADRAXER 2 SUV	225/65//R17 - 102H / 3 mm
	KLEBER KLEBER-QUADRAXER 2 SUV	225/65//R17 - 102H / 3 mm

Cosmetic Damage

19 Danni



4 Danni



Component		Damage	Comments
1	Aeration Grid / Front Center	Interior / Broken	
2	Steering Wheel / Front	Interior / Worn - out	
3	Seat / Front Left	Interior / Worn - out	
4	Panel Filling / Front Left	Interior / Worn - out	
5	Fender / Front Right	Paint / Scratch / Line	
6	Bumper / Front	Bodywork / Dent	
7	Hood	Paint / Scratch / Line	
8	Windshield / Front	Glass Break / Impact	
9	Bumper / Front	Bodywork / Breakage	
10	Fender / Front Left	Bodywork / Dent	
11	Rim / Front Left	Out of Bodywork / Scratch	
12	Door / Front Left	Bodywork / Dent	


13	Door / Back Left	Paint / Scratch / Line
14	Rim / Back Left	Out of Bodywork / Scratch
15	Fender / Back Left	Bodywork / Dent
16	Fog Light / Back Right	Glass Break
17	Bumper / Back	Bodywork / Breakage
18	Tailgate	Bodywork / Dent
19	Fender / Back Right	Paint / Scratch / Line
20	Door / Back Right	Bodywork / Dent
21	Rocker Panel / Center Right	Bodywork / Dent
22	Door / Front Right	Bodywork / Dent
23	Roof	Bodywork / Dent / Hail Area



1. Aeration Grid / Front Center
Interior / Broken -



2. Steering Wheel / Front
Interior / Worn - out -



3. Seat / Front Left
Interior / Worn - out -




4. Panel Filling / Front Left
Interior / Worn - out -



5. Fender / Front Right
Paint / Scratch / Line -



6. Bumper / Front
Bodywork / Dent -



7. Hood
Paint / Scratch / Line -



8. Windshield / Front
Glass Break / Impact -



9. Bumper / Front
Bodywork / Breakage -



10. Fender / Front Left
Bodywork / Dent -



11. Rim / Front Left
Out of Bodywork / Scratch -



12. Door / Front Left
Bodywork / Dent -



13. Door / Back Left
Paint / Scratch / Line -



14. Rim / Back Left
Out of Bodywork / Scratch -



15. Fender / Back Left
Bodywork / Dent -



16. Fog Light / Back Right
Glass Break -



17. Bumper / Back
Bodywork / Breakage -



18. Tailgate
Bodywork / Dent -



19. Fender / Back Right
Paint / Scratch / Line -



20. Door / Back Right
Bodywork / Dent -



21. Rocker Panel / Center Right
Bodywork / Dent -



22. Door / Front Right
Bodywork / Dent -



23. Roof
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested