



CHEVROLET Spark

Spark 1.0

VIN NO KL1MF4819DC544465
Registration Number 19DC544465



MOT Date

2026-03-01

Last Service



Number of Owners

3

Last Service Mileage



Number of Keys

2

First Registration Date

2013-03-15

Odometer Reading

131510 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251007082252
Inspection Date / Place	2025-10-07 / SULOJA Brackel	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	995
Engine Size	1.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	118
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Auxiliary Socket	Stability control
Radio	Airbag Status	Anti-lock braking	Remote central locking
CD Player			

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	14
------------------	-----	------------------	----

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

25 Schäden




2 Schäden



Component		Damage	Comments
1	Roof	Bodywork / Dent	
2	Hood	Bodywork / Dent / Dent	
3	Panel Filling / Back Right	Interior / Scratched	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Door / Back Left	Paint / Scratch / Scuff	
6	Door / Front Left	Bodywork / Dent / Dent	
7	Door / Back Right	Bodywork / Dent / Dent	
8	Bumper / Back	Bodywork / Dent / Dent	
9	Seat / Front Left	Interior / Ripped	
10	Fender / Front Left	Paint / Poor Previous Repair	
11	Door / Front Left	Paint / Poor Previous Repair	
12	Rocker Panel / Center Right	Paint / Scratch / Scuff	

13	Bumper trim	Paint / Scratch / Scuff
14	Door / Front Right	Bodywork / Dent / Dent
15	Door / Back Left	Paint / Poor Previous Repair
16	Side Panel / Back Left	Bodywork / Dent / Dent
17	Tailgate	Paint / Scratch / Scuff
18	Door / Back Left	Paint / Scratch / Scuff
19	Bumper / Front	Paint / Scratch / Scuff
20	Bumper / Back	Paint / Scratch / Scuff
21	Bumper / Back	Bodywork / Breakage / Hole
22	Door / Front Left	Bodywork / Dent / Dent
23	Fender / Front Right	Bodywork / Dent / Dent
24	Door / Back Right	Paint / Scratch / Scuff
25	Side Panel / Back Left	Paint / Scratch / Scuff
26	Side Panel / Back Right	Bodywork / Dent / Dent
27	Bumper / Front	Paint / Scratch / Scuff
28	Bumper / Back	Paint / Scratch / Scuff



1. Roof
Bodywork / Dent -




2. Hood
Bodywork / Dent / Dent -




3. Panel Filling / Back Right
Interior / Scratched -




4. Bumper / Front
Paint / Scratch / Scuff -



5. Door / Back Left
Paint / Scratch / Scuff -



6. Door / Front Left
Bodywork / Dent / Dent -




7. Door / Back Right
Bodywork / Dent / Dent -



8. Bumper / Back
Bodywork / Dent / Dent -



9. Seat / Front Left
Interior / Ripped -



10. Fender / Front Left
Paint / Poor Previous Repair -



11. Door / Front Left
Paint / Poor Previous Repair -



12. Rocker Panel / Center Right
Paint / Scratch / Scuff -



13. Bumper trim
Paint / Scratch / Scuff -




14. Door / Front Right
Bodywork / Dent / Dent -



15. Door / Back Left
Paint / Poor Previous Repair -




16. Side Panel / Back Left
Bodywork / Dent / Dent -




17. Tailgate
Paint / Scratch / Scuff -



18. Door / Back Left
Paint / Scratch / Scuff -



19. Bumper / Front
Paint / Scratch / Scuff -



20. Bumper / Back
Paint / Scratch / Scuff -




21. Bumper / Back
Bodywork / Breakage / Hole -



22. Door / Front Left
Bodywork / Dent / Dent -



23. Fender / Front Right
Bodywork / Dent / Dent -



24. Door / Back Right
Paint / Scratch / Scuff -



25. Side Panel / Back Left
Paint / Scratch / Scuff -



26. Side Panel / Back Right
Bodywork / Dent / Dent -



27. Bumper / Front
Paint / Scratch / Scuff -



28. Bumper / Back
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly 

Engine

Engine Noise		Fume Quantity	
Power Loss		The Gears Scratch / Skip / Abnormal Operation	

Brake

Brake System Anomaly 

Clutch

Clutch Functioning 

General

Test Driven Status 

-  **No troubles detected, good condition or correct tests, according to vehicle age and mileage**
-  **Damages or malfunction detected that requires repairs by the buyer**
-  **Not applicable**
-  **Not tested**

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)