

# HYUNDAI IONIQ Ioniq Plug-in 141 ch Executive



VIN NO KMHC751DGMU235993 Registration Number FW003DZ

MOT Date

★-

Last Service

**#**-

**Number of Owners** 

**:2:** -

Last Service Mileage

n-

Number of Keys

**P**1

First Registration Date

**2**020-12-29

**Odometer Reading** 

**№** 163525 km

Country First Registered

8

### Inspection Report Summary

Customer BCAuto Encheres Report Number P20250903060906

Inspection Date / Place 2025-09-03 / BCA BOUCHAIN Cosmetic Grade 1

## Vehicle Summary

Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Gearbox Type	Auto clutch
Colour	Black	Engine Size (cc)	1580
Engine Size	1.6	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	

#### Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





























# Equipment

Central locking	Electrically folding wing mirrors	Rear parking sensors	Stability control
Cruise control	Front parking sensors	Satellite navigation	Electrically adjustable seats
Radio	Alloys wheels	Tow ball	Front fog lamps

Power assisted steering


## **Equipment Details**

Seat Heating	Front	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Glass		


# Wheels & Tyres

Left Rear Tyre Depth	6	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Right Front Tyre Depth	5

## Cosmetic Damage



	Component	Damage	Comments
1	Rim / Front Left	Out of Bodywork / Scratch	
2	Rim / Back Left	Out of Bodywork / Scratch	



1. Rim / Front Left
Out of Bodywork / Scratch -

2. Rim / Back Left Out of Bodywork / Scratch -

## **Mechanical Condition**

Levels			
Coolant Fluid - Condition	<b>⊘</b>	Oil - Condition	•
Level - Oil	•	Coolant Fluid	•
Brakes Fluid	•		
Tyres			
Presence Anti-Theft Lock Nut	•		
Dashboard Lights			
ABS Warning Light	•	Diesel Particulate Filter Light	NA
ESP Fault/Traction Control Malfunction Light	•	4WD Light	NA
Dashboard Working	•	Engine Light	•
Oil Pressure Warning Light	•	Airbag Warning Light	•
Brake Warning Light	•	Level - Fuel / Battery	30
Transmission Warning Light	•	Service Light	•
Steering Fluid Level	NA		
Equipments Test			
Electric Windows	<b>⊘</b>	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	•
Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	•
Central Locking	•	Audio Equipment	•
Navigation System	•	AC / Heating System	•
Parking Sensors / Cameras Functioning	•		
Hybrid/EV			
Charge Port Condition	•	Hybrid System Fault	•
Charge lead 1 condition /Charge lead 2 condition	<b>⊘</b>		
Engine			
Cross Member	<b>⊘</b>	Serpentine Belt	•

Control Liquid Leak

## **Test Drive Inspection**

Test Drive			
Engine functioning	•	Engine / Aux Belt / Pulley Noise	•
Vehicle Starts	•	Steering Noise/Gripping	•
Engine Power	<b>©</b>	Smoke Quantity	•
Transmission	<b>©</b>	Clutch Functioning	•
Steering	<b>⊘</b>	Brakes Functionning	•
—	d condition or correct tests, accord letected that requires repairs by th	= = =	

#### **Disclaimer Section**

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.