



Hyundai Kona (UKL): 2BGX678

Vinnumber:	KMHK3817GMU831317	Versionname:	Kona Techno 1.6CRDi mHEV 136pk/cv 5p 7-DCT
First Registrationdate:	22/11/2021	Fiscalpower:	
Expertise Mileage:	87786	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	HD		

Tyres

	215/55/17/98 V			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Pirelli: 6 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	6.0			
Tyre profile depth RR	6.0			
Tyre size FL	215/55 R 17 98 V			
Tyre size FR	215/55 R 17 98 V			
Tyre size RL	215/55 R 17 98 V			
Tyre size RR	215/55 R 17 94 W			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Summer			
Tyre make FL	265			
Tyre make FR	265			
Tyre make RL	265			
Tyre make RR	264			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior, Dirty, Cleaning





Engine, Not functioning (well), Check




Bumper spoiler F, Deformed / Strained, Replace



Bumper moulding F, Scratch(es), Replace



Alloy rim FL, Scratch(es), Repair and paint (complete)



Rubber seal for boot lid, Broken, Replace



Bumper R, Scratch(es), Acceptable



Alloy rim RR, Deformed / Strained, Replace



Alloy rim FR, Scratch(es), Repair and paint (complete)



Tyre FR, Worn, Check



Bodywork, Not original part, Remove lettering

