


Vehicle details

VIN	KMHK381HF LU102806	Brand	HYUNDAI	Maintenance date	-
Licence Plate	J3-03-LG	Model	KONA Fashion Electric 39 kWh 5d	Maintenance mileage	-
Registration date	21/10/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	73 430 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	19/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 215/55/17 Summer 4.0 mm			Michelin 215/55/17 Summer 4.0 mm	
Michelin 215/55/17 Summer 6.0 mm			Michelin 215/55/17 Summer 6.0 mm	

Exterior

1		Part	Door
		Position	Front left
2		Damages	Dented
		Severity	Diameter (mm) > 20
3		Repair mode	Smart Repair
4		Part	Wing
		Position	Front right
5		Damages	Dent & Chips
		Severity	Diameter (mm) > 20
		Repair mode	Repair
		Part	Bumper
		Position	Front
		Damages	Scratched
		Severity	Length (cm) > 10
		Repair mode	Repair