



Vehicle details

VIN	KMHK581EG LU040007	Brand	HYUNDAI	Maintenance date	-
Licence Plate	J9-40-LH	Model	KONA 1.6 GDI HEV Premium 5d	Maintenance mileage	-
Registration date	04/09/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	136 855 km	Engine size	1591	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Dekra Ayvens		
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 225/45/18 Summer 5.0 mm		Michelin 225/45/18 Summer 5.0 mm	
Michelin 225/45/18 Summer 6.5 mm		Michelin 225/45/18 Summer 6.5 mm	

Exterior

1		Part Position Damages Severity Repair mode	Wing moulding Front left Scratched Length (cm) > 10 Repair	2		Part Position Damages Severity Repair mode	Wing Front left Scratched Length (cm) > 10 Repair
3		Part Position Damages Severity Repair mode	Door Front left Scratched Length (cm) > 10 Repair	4		Part Position Damages Severity Repair mode	Door Back left Scratched Length (cm) > 10 Repair
5		Part Position Damages Severity Repair mode	Wing Back right Scratched - Repair	6		Part Position Damages Severity Repair mode	Alloy wheel 18" Back right Scratched - Lumpsum repair
7		Part Position Damages Severity Repair mode	Alloy wheel 18" Front right Scratched - Lumpsum repair	8		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair
9		Part Position Damages Severity Repair mode	Lower bumper Front Scratched Length (cm) > 10 Repair				