



## status report

Report number:	0000000828639-EN968	Off. Mark :	HH- BC 310E
reference number:	30894255		

### Vehicle Data

#### Hyundai Ioniq 5 (05.2021->) Basis Elektro

Vehicle identification number .:	<b>KMHKM81BFNU053728</b>	mileage read:	<b>112363 km</b>
First Registration / construction Year:	<b>02.03.2022 / 2021</b>	Inspection date/place:	<b>10.03.2025 50827 Köln</b>
Bodywork:		Body type:	<b>hatchback</b>
fuel:	<b>Electric</b>	Transmission type:	<b>Automatic</b>
GPS sat nav disk:		Displacement / power:	<b>0 ccm / 125 kW (170 PS)</b>
Drive type:		Paint:	<b>Atlas White / SOL</b>
Type of paint:	<b>Uni ( 2 layer)</b>	Doors / seats:	<b>5 / 5</b>
Number of keys:	<b>2</b>	Next HU / AU:	<b>2025-03 / 2025-03</b>
cushion type:	<b>Substance</b>	Service book available:	
Interior Color:		Maintained service book:	
smoking vehicle:	<b>No</b>	Last service km / on the:	<b>92005 / 2024-07-03</b>
Vehicle roadworthy:	<b>Yes</b>	Submitted vehicle documents:	<b>Registration Certificate</b>
State outside:	<b>2 - Good</b>	condition inside:	<b>2 - Good</b>

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



### Mounted tires

	Winter tires
Tyre / wheel type:	/// 5 mm
2nd axis - Left / states .	/// 5 mm
2nd axis - right / states .	/// 5 mm
1st axis - Left / states .	/// 5 mm
1st axis - right / states .	/// 5 mm
Traffic Safety:	

### Unmounted tires

	Summer tires	Aluminium original
Tyre / wheel type:	-	-/-/- 4 mm
1st axis - Left / states .	-	-/-/- 4 mm
1st axis - right / states .	-	-/-/- 4 mm
2nd axis - Left / states .	-	-/-/- 4 mm
2nd axis - right / states .	-	-/-/- 4 mm
Traffic Safety:	Roadworthy	

### Series

- |   |   |
|---|---|
| <ul style="list-style-type: none"> <li>• 3rd brake light</li> <li>• Storage bag on front seat backrests</li> <li>• Airbag front passenger side can be switched off</li> <li>• Active brake light (ESS)</li> <li>• Anti-lock braking system (ABS)</li> <li>• Audio-Navigationssystem</li> <li>• Outside mirror electr. anklappbar</li> <li>• Exterior mirror painted</li> <li>• Flashing light integrated in the exterior mirror</li> <li>• Rear Parking Sensors</li> <li>• Electr. Brake force distribution</li> <li>• Electron. Stability control (ESC) with brake assistant</li> <li>• Fahrassistenz-System: Aufmerksamkeits-Assistent</li> <li>• Driving assistance system: Autonomous emergency braking function including turning function (FCA-JT)</li> <li>• Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)</li> </ul> | <ul style="list-style-type: none"> <li>• 6 Lautsprecher</li> <li>• Airbag passenger side</li> <li>• Airbag driver side</li> <li>• Alarm system</li> <li>• Drive type: rear-wheel drive</li> <li>• Audio system: Radio RDS</li> <li>• Outside mirror electr. adjustable and heated, both</li> <li>• Außenspiegel Unterschale schwarz lackiert</li> <li>• Roof spoiler</li> <li>• Automatic switch-on for driving lights / light sensor</li> <li>• Elektromotor 125 kW (cont. 42 kW)</li> <li>• Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)</li> <li>• Fahrassistenz-System: Autobahnassistent (Highway Driving Assist, HDA)</li> <li>• Driving assistance system: Autonomous emergency braking function including cyclist detection (FCA-Cyc.)</li> <li>• Driving assistance system: Autonomous emergency braking function including pedestrian detection (FCA-Ped.)</li> </ul> |
|---|---|

- Driver assistance system: hill start assist
- Driver assistance system: high beam assistant
- Driving Assistance System: Multi Collision Brake
- Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA)
- Window regulator electr. with anti-trap protection
- Handsfree Bluetooth
- Getriebe für Elektrofahrzeug
- Cup holder in front
- Handschuhfach Schublade
- Rear window heatable
- HV-Batterie 58 kWh (Lithium-Ionen)
- Isofix seats for child seat
- Automatic climate control 2 zones
- Headrests adjustable at the back
- Charging cable with Type 2 plug
- Lumbar support seat front left, electr. adjustable
- Lenkrad heizbar
- Steering column (steering wheel) height adjustable
- LED reading lights front and rear
- LM rims 7.5x19
- Mineraleffekt-Lackierung Mystic-Olive
- Center armrest front
- Notladekabel (ICCB)
- Radio reception digital (DAB +)
- Tire repair kit
- Backup camera
- Rear seat back divided / foldable
- Window fogging detection / control
- Scheinwerfer Voll-LED
- Seitenairbag vorn mitte (Central Airbag)
- Service system: Remote Services (Blue Link)
- Seatbelts height adjustable
- Seat front right height adjustable
- Driver assistance system: Driving profile selection (Drive Mode)
- Fahrassistenz-System: Insassenalarm (ROA)
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Fahrassistenz-System: Verkehrszeichenerkennung, erweitert (Geschwindigkeits-Regel-/Begrenzeranlage)
- Fensterheber elektrisch vorn und hinten, mit Auf-/Ab-Automatik
- Luggage compartment cover / roller blind
- Getränkehalter hinten
- Pretensioners
- Rear lights LED (pixel design)
- Rear window wiper
- Instrumentenanzeige Farbdisplay 12,25 Zoll
- Body: 5-door
- Head airbag system
- Kühlergrill, Aktive Luftklappen, regelbar
- Ladevorrichtung On-Board-Lader (3-Phasen)
- Steering wheel (leather) with multifunction
- Steering wheel with paddle shifters
- Steering column (steering wheel) longitudinally adjustable
- Headlamp leveling
- Rear air vents
- Rear center armrest
- Navigation-Based Adaptive Cruise Control (Cruise Control) with Adaptive Cruise Control (NSCC)
- Parking brake electric (EPB)
- Tires 235/55 R19 ... V
- Tire pressure monitoring system
- Rücksitzbank verschiebbar
- Schalt-/Wählhebel (Shift by Wire)
- Rain-sensing wipers
- Side airbag in front
- Seitenschutzleisten schwarz
- Power steering
- Seat front left height adjustable
- Seat cover / upholstery: fabric

- |  |   |
|--|---|
| <ul style="list-style-type: none"> <li>• Heated seats in the front</li> <li>• Smartphone Schnittstelle (Apple CarPlay &amp; Android Auto)</li> <li>• Start-stop button</li> <li>• Daytime running light LED</li> <li>• Türgriffe außen ausfahrbar / versenkbar</li> <li>• USB-Anschluss hinten</li> <li>• Glazed tinted</li> <li>• Immobilizer (electronic)</li> </ul> | <ul style="list-style-type: none"> <li>• Smart key</li> <li>• Sonnenblenden mit Spiegel</li> <li>• Steckdose (12V-Anschluß) vorn</li> <li>• Touchscreen color display (12.25 inches)</li> <li>• Door handles outside body color</li> <li>• USB-Anschluss Mittelkonsole</li> <li>• Seat belt warning system, driver / passenger side</li> <li>• Central locking with remote control</li> </ul> |
|--|---|

### Special Features

- Special paint finish Atlas White Uni

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

### General exam

<b>test drive:</b>	<b>Conducted limited</b> Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .
<b>Subfloor Inspection:</b>	<b>Not performed</b> A visit to the underbody of the car was not performed .
<b>Mileage plausible:</b>	<b>Not testable</b> Not testable
<b>reference:</b>	
<b>Note Road Safe:</b>	

### Accident claims investigation

<b>Rep. Predamages / -height gross:</b>	
<b>Layers of paint thickness measurement:</b>	
<b>Existing collision damage:</b>	<b>Not established</b> On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
<b>reference:</b>	

### Overview of technical examination

<b>Air conditioning:</b>	Examined limited	✗	<b>Lighting system:</b>	examined limited	✗
<b>Sunroof / convertible:</b>	unavailable	✗	<b>Seat heating:</b>	In order	✓
<b>Brake system:</b>	examined limited	✗	<b>Engine running:</b>	examined limited	✗

### Implemented technical examination

<b>air conditioning:</b>	The air conditioning system could be tested only restricted during the visit .
<b>lighting system:</b>	The Lichtenanlage could be considered limited to the tour date .
<b>Sunroof / convertible:</b>	unavailable
<b>Seat heating:</b>	In order
<b>brake system:</b>	The braking system has been tested by a visual inspection .
<b>engine running:</b>	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
<b>reference:</b>	*

## Damage



### Exterior and Styling

	Component	Damage	Rep kind
1.	Rear Bumper	Damaged	Replace

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable ( small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



## Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside



instrument cluster



mileage




center console



key



key



Service book / proof





engine compartment



rims



tires



tires



tires



tires





1. Rear Bumper  
**Damaged - Replace**