



Hyundai Santa Fe: N198KG

Vinnumber:	KMHS3811BMU002259	Versionname:	Santa Fe 1.6 T-GDI HEV 169kW Comfort Smart 7STR automaat
First Registrationdate:	3/11/2021	Fiscalpower:	
Expertise Mileage:	187610	Power Kw:	132
Bodytype:		Body colour:	Phantom Black pearl
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	593
Number of seats:	7		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Roof rack

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 55 / 19 / 105 / V / Aluminium	4,0 mm	Michelin	Summer
	Right	235 / 55 / 19 / 105 / V / Aluminium	3,5 mm	Michelin	Summer
Rear	Left	235 / 55 / 19 / 105 / V / Aluminium	4,5 mm	Continental	Summer
	Right	235 / 55 / 19 / 105 / V / Aluminium	3,8 mm	Continental	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Wheel arch cover RL, Dent(s) and scratch(es), Replace



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Repair and paint (complete)



Wheel arch cover RR, Scratch(es), Replace




Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)





Bumper moulding R, Dent(s) and scratch(es), Replace

