



HYUNDAI Santa Fe

Grand Santa Fe 2.2 CRDI 4WD Automatik



VIN NO KMHSR81XDFU126757
Registration Number XDFU126757

MOT Date

2027-04-01

Last Service



Number of Owners

1

Last Service Mileage



Number of Keys

2

First Registration Date

2016-02-23

Odometer Reading

406796 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251008115903
Inspection Date / Place	2025-10-08 / SULOJA Brackel	Cosmetic Grade	9


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	2199
Engine Size	2.2	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	6
Seat Covering Name	Black	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	199
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	USB Socket	Alloys wheels	Auxiliary Socket
Cruise control	Front fog lamps	Remote adjusting wing mirrors	Reversing Camera
Seatventilation	Stability control	Electrically adjustable seats	Electrictailgate
Radio	Rear parking sensors	Trip Computer	Airbag Status
Anti-lock braking	Bluetooth telephone interface	Diesel particulate filter	Front parking sensors
Remote central locking	Satellite navigation	Split folding rear seats	CD Player
Electrically folding wing mirrors	Leather steering wheel	Rain sensitive windscreen wipers	Rear sunblind

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Seat Heating	Front and Rear		

Wheels & Tyres


Right Rear Tyre Depth	4	Left Rear Tyre Depth	4
Right Front Tyre Depth	4	Left Front Tyre Depth	4

Cosmetic Damage

38 Schäden



8 Schäden



Component		Damage	Comments
1	Backrest Cover / Front Left	Interior / Scratched	
2	Door Joint / Front Left Middle	Bodywork / Breakage / Crack	
3	Door / Back Right	Bodywork / Dent / Dent	
4	Seat / Front Right	Interior / Scratched	
5	Bumper / Back	Paint / Scratch / Scuff	
6	Bumper / Back	Paint / Scratch / Scuff	
7	Roof	Paint / Corrosion	
8	Bumper / Back	Paint / Scratch / Scuff	
9	Door / Back Left	Paint / Scratch / Scuff	
10	Rim / Back Right	Paint / Corrosion	
11	Glovebox	Interior / Scratched	
12	Seat / Front Right	Interior / Scratched	

13	Rim / Front Right	Out of Bodywork / Scratch
14	Rim / Front Left	Paint / Corrosion
15	Bumper / Front	Paint / Scratch / Scuff
16	Bumper / Front	Bodywork / Breakage / Hole
17	Rim / Back Left	Paint / Corrosion
18	Door / Back Left	Paint / Scratch / Scuff
19	Tailgate	Bodywork / Dent / Dent
20	Door / Back Left	Paint / Scratch / Scuff
21	Bumper / Front	Bodywork / Breakage / Hole
22	Door / Front Right	Bodywork / Dent / Dent
23	Door / Front Left	Paint / Scratch / Scuff
24	Door Side Molding / Back Right	Paint / Scratch / Scuff
25	Seat / Back Left	Interior / Scratched
26	Tailgate	Bodywork / Dent / Dent
27	Door / Front Right	Paint / Scratch / Scuff
28	Door / Front Left	Bodywork / Dent / Dent
29	Seat / Front Left	Interior / Scratched
30	Hood	Paint / Poor Previous Repair
31	Tailgate	Paint / Scratch / Scuff
32	Seat / Front Left	Interior / Holed
33	Side Panel / Back Left	Paint / Scratch / Scuff
34	Side Panel / Back Left	Bodywork / Dent / Dent
35	Roof Upholstery	Interior / Holed
36	Fender / Front Left	Paint / Scratch / Scuff
37	Fender / Front Right	Paint / Scratch / Scuff
38	Pillar / Front Right	Paint / Scratch / Scuff
39	Bumper / Front	Paint / Scratch / Scuff
40	Bumper / Front	Bodywork / Breakage / Hole
41	Side Panel / Back Left	Paint / Scratch / Scuff

42	Hood	Paint / Scratch / Scuff
43	Hood	Paint / Corrosion
44	Bumper / Front	Bodywork / Breakage / Hole



1. Backrest Cover / Front Left
Interior / Scratched -



2. Door Joint / Front Left Middle
Bodywork / Breakage / Crack -



3. Door / Back Right
Bodywork / Dent / Dent -



4. Seat / Front Right
Interior / Scratched -



5. Bumper / Back
Paint / Scratch / Scuff -



6. Bumper / Back
Paint / Scratch / Scuff -



7. Roof
Paint / Corrosion -



8. Bumper / Back
Paint / Scratch / Scuff -



9. Door / Back Left
Paint / Scratch / Scuff -



10. Rim / Back Right
Paint / Corrosion -



11. Glovebox
Interior / Scratched -



12. Seat / Front Right
Interior / Scratched -



13. Rim / Front Right
Out of Bodywork / Scratch -



14. Rim / Front Left
Paint / Corrosion -



15. Bumper / Front
Paint / Scratch / Scuff -



16. Bumper / Front
Bodywork / Breakage / Hole -



17. Rim / Back Left
Paint / Corrosion -



18. Door / Back Left
Paint / Scratch / Scuff -



19. Tailgate
Bodywork / Dent / Dent -



20. Door / Back Left
Paint / Scratch / Scuff -



21. Bumper / Front
Bodywork / Breakage / Hole -




22. Door / Front Right
Bodywork / Dent / Dent -



23. Door / Front Left
Paint / Scratch / Scuff -



24. Door Side Molding / Back Right
Paint / Scratch / Scuff -



25. Seat / Back Left
Interior / Scratched -



26. Tailgate
Bodywork / Dent / Dent -




27. Door / Front Right
Paint / Scratch / Scuff -




28. Door / Front Left
Bodywork / Dent / Dent -



29. Seat / Front Left
Interior / Scratched -



30. Hood
Paint / Poor Previous Repair -



31. Tailgate
Paint / Scratch / Scuff -



32. Seat / Front Left
Interior / Holed -



33. Side Panel / Back Left
Paint / Scratch / Scuff -



34. Side Panel / Back Left
Bodywork / Dent / Dent -



35. Roof Upholstery
Interior / Holed -



36. Fender / Front Left
Paint / Scratch / Scuff -



37. Fender / Front Right
Paint / Scratch / Scuff -



38. Pillar / Front Right
Paint / Scratch / Scuff -



39. Bumper / Front
Paint / Scratch / Scuff -



40. Bumper / Front
Bodywork / Breakage / Hole -



41. Side Panel / Back Left
Paint / Scratch / Scuff -



42. Hood
Paint / Scratch / Scuff -



43. Hood
Paint / Corrosion -



44. Bumper / Front
Bodywork / Breakage / Hole -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	AC / Heating System	✓
Main & Spare Keys Functioning	✓	Parking Sensors / Cameras Functioning	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)