

Inspection Protocol

KIA EV6 77.4 KWH AWD, 325HK, 2023

Vehicle information

License plate	EBO152	Inspected by	T.H.
Year model	2023	Date of inspection	2025-12-01
Manuf. year/month	2023-03	City	Björkvik
First day in traffic	2023-05	Keys	1
Colour	Grå	Service book	Ja
Mileage	76 760 km	Latest service	2025-05-13
Fuel	El (EV)	Mileage at the latest service	57 990 km
Transmission	Automat	Summer tires	19" alu-fälg 5/5/5/5
Engine effect	239 kW	Winter tires	alu-fälg odubbbat 4/4/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Keys	Extra key missing		230 €
Recond	Extra recond	Smutsig interiör	270 €
Door, Front left	Dörruppslag		-
Door, Rear left	Scratches 30-100 mm		100 €
Wing, Rear left	Scratches above 100 mm		180 €
Boot lid, Boot lid	Scratches above 100 mm		230 €
Bumper, Rear	Repor, 3-10 cm		100 €
Wing, Rear right	Scratches below 30 mm		70 €
Door, Rear right	Dents below 30 mm		70 €
Door, Front right	Dents below 30 mm		70 €
Door, Righ side mirror	Scratches 30-100 mm		100 €
Bumper, Front	Cracks 30 mm-100 mm		300 €
Bonnet	Chips, several		200 €

Total excl. VAT 1 920 €


Images

[See all images in large format](#)

























Dörr Vänster fram Dörruppslag



Dörr Vänster bak Repor 3-10 cm 1 100 kr

