


## Vehicle details

|                   |                    |              |                                    |                           |               |
|-------------------|--------------------|--------------|------------------------------------|---------------------------|---------------|
| VIN               | KNACC81CG L5313236 | Brand        | KIA                                | Maintenance date          | -             |
| Licence Plate     | G9-94-BF           | Model        | Niro 1.6 GDi Hybrid DynamicLine 5d | Maintenance mileage       | -             |
| Registration date | 20/09/2019         | Year         | 2019                               | Exterior Color            | Grey Metallic |
| Odometer          | 48 439 km          | Engine size  | 1580                               | interior Color            | Black         |
| Fuel              | Hybrid petrol      | Body Type    | -                                  | Next technical inspection | -             |
| Seats             | -                  | Transmission | Automatic                          | CO2                       | -             |
| Doors             | 5                  | Gears        | -                                  |                           |               |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 27/05/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| GPS system                 | ✓ |
| Alloy wheel rims           | ✓ |
| Automatic Gearbox          | ✓ |
| Metallic paint             | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Side rails                 | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |


## Removable element

|            |   |
|------------|---|
| Load cover | ✓ |
|------------|---|

## Technical Document

|                  |   |
|------------------|---|
| Spare key        | ✗ |
| User manual      | ✓ |
| Warranty booklet | ✓ |
| Remote key       | ✓ |

## Tyres



## Exterior

2



● ● ●

|             |                    |
|-------------|--------------------|
| Part        | Wing               |
| Position    | Front left         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

3



● ●

|             |            |
|-------------|------------|
| Part        | Step plate |
| Position    | Back left  |
| Damages     | Dented     |
| Severity    | -          |
| Repair mode | For info   |

4



● ●

|             |              |
|-------------|--------------|
| Part        | Step plate   |
| Position    | Back right   |
| Damages     | Dent & Chips |
| Severity    | -            |
| Repair mode | For info     |

5



● ●

|             |                  |
|-------------|------------------|
| Part        | Roof post A/B/C  |
| Position    | Right            |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

6



● ●

|             |                  |
|-------------|------------------|
| Part        | Lower bumper     |
| Position    | Front            |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

7



● ●

|             |                  |
|-------------|------------------|
| Part        | Spoiler          |
| Position    | Front            |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

### Interior damage

1



|             |           |
|-------------|-----------|
| Part        | Spare key |
| Position    | -         |
| Damages     | Missing   |
| Severity    | -         |
| Repair mode | Replace   |