

H-503-XX Kia Niro 1.6 GDi Hybrid DynamicLine

Dealer	HEDIN AUTOMOTIVE 2R KERKRADE te KERKRADE	Datum	17/06/2021	Km stand	6157
	Onh 5.000 Km				
Dealer	HEDIN AUTOMOTIVE 2R HEERLEN KI te HEERLEN	Datum	14/06/2022	Km stand	18824
	Onh 30.000 Km				
	Interieur Int luchtfilter				
	Remmen Remvloeistof				
	Koel-/verw systKoelvl/antivrie				
	Ruitenspr.bijvullen				
	Carrosserie Batterij				
Dealer	HEDIN AUTOMOTIVE 2R HEERLEN KI te HEERLEN	Datum	13/06/2023	Km stand	30791
	Onh 45.000 Km				
	Brst. algemeen Luchtfilter				
	Koel-/verw systKoelvl/antivrie				
	Ruitenspr.bijvullen				
	Ruitenwiss.blad V				
	Ruitewiss.blad A				
Dealer	HEDIN AUTOMOTIVE 2R HEERLEN KI te HEERLEN	Datum	11/06/2024	Km stand	41984
	Interieur Int luchtfilter				
	Remmen Remvloeistof				
	APK icm beurt				
	Onh 60.000 Km				

H-503-XX Kia Niro 1.6 GDi Hybrid DynamicLine

Schadedatum	Oorzaak	Schade aan derden	Verhaalbaar	Aard schade
06/16/2023	Achteruit rijden	Nee	Ja	Rechterachterzijde
08/13/2024	Hagel	Nee	Nee	Bovenzijde/Dak