


Vehicle details

VIN	KNACC81CG M5458654	Brand	KIA	Maintenance date	-
Licence Plate	L5-48-KV	Model	Niro 1.6 GDi Hybrid DynamicPlusLine 5d	Maintenance mileage	-
Registration date	18/06/2021	Year	2021	Exterior Color	Black Metallic
Odometer	155 501 km	Engine size	1580	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	25/06/2025	Inspection loc.	Dekra Ayvens		
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Pirelli 205/60/16 Summer 7.0 mm		Bridgestone 205/60/16 Summer 5.5 mm	
Bridgestone 205/60/16 Summer 6.0 mm		Pirelli 205/60/16 Summer 7.0 mm	

Exterior

6		Part Position Damages Severity Repair mode	Roof post A/B/C Left Dented Diameter (mm) > 20 Smart Repair	7		Part Position Damages Severity Repair mode	Step plate Back left Dent & Chips - For info
8		Part Position Damages Severity Repair mode	Bumper Back Dented Diameter (mm) > 20 Repair	9		Part Position Damages Severity Repair mode	Step plate Front right Scratched - For info
10		Part Position Damages Severity Repair mode	Bumper protection film Front right Scratched Length (cm) > 10 Repair	11		Part Position Damages Severity Repair mode	Lower bumper Front Scratched Length (cm) > 10 Repair
12		Part Position Damages Severity Repair mode	Windscreen - Stone impact - For info				

Interior damage

1		Part Position Damages Severity Repair mode	Panel lining wood/fabric Back right Scratched - Smart Repair				
2		Part Position Damages Severity Repair mode	Interior tailgate lining Down Scratched - Smart Repair	3		Part Position Damages Severity Repair mode	Panel lining wood/fabric Back left Scratched - Smart Repair
4		Part Position Damages Severity Repair mode	Boot carpet - Stained/dirty - Cleaning	5		Part Position Damages Severity Repair mode	Dashboard Front right Scratched - Smart Repair