



Kia Niro: H037GH

Vinnnummer:	KNACC81GFK5025343	Versionname:	e-Niro 150kW / 64kWh Executive Line automaat
First Registrationdate:	25/01/2020	Fiscalpower:	
Expertise Mileage:	112833	Power Kw:	150
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	531
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

215/55/17/98 V				
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 4,7 mm
	Re.L.	Bridgestone: 5,4 mm	Re.R.	Bridgestone: 3,1 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				4.7
Tyre profile depth RL				5.4
Tyre profile depth RR				3.1
Tyre size FL				215/55 R 17 098 V
Tyre size FR				215/55 R 17 098 V
Tyre size RL				215/55 R 17 098 V
Tyre size RR				215/55 R 17 098 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Wing FL, Scratch(es), Polish



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Wheel arch cover FL, Scratch(es), Replace



Bonnet, Stone chip(s), Repair and paint (complete)



Shutter / cover F, Broken, Replace



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Wheel arch cover RR, Scratch(es), Replace



Tailgate / Boot, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)

