


Vehicle details

VIN	KNADA811A L6413564	Brand	KIA	Maintenance date	-
Licence Plate	H0-18-ZH	Model	Stonic 1.0 T-GDi 74 kW ActieAuto 5d DynamicLine AP	Maintenance mileage	-
Registration date	27/06/2020	Year	2020	Exterior Color	Black Metallic
Odometer	64 555 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	08/09/2025	Inspection loc.	Ayvens Veghel		
-----------------	------------	-----------------	---------------	--	--



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 205/55/17 Summer 4.0 mm		Pirelli 205/55/17 Summer 4.0 mm		
Continental 205/55/17 Summer 5.0 mm		Continental 205/55/17 Summer 3.5 mm		

Exterior

1



Part

Wing

Position

Front left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

3



Part

Bumper

Position

Back left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

4



Part

Unpainted bumper

Position

Back left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

6



Part

Step plate

Position

Back right

Damages

Scratched

Severity

-

Repair mode

For info

●

●

7



Part

Door

Position

Back right

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

●

●

8



Part

Door

Position

Front right

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

Interior damage

2



●●●

Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5



●●●

Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Smart Repair