

Vehicle details

VIN	KNADA811A L6440199	Brand	KIA	Maintenance date	-
Licence Plate	J2-08-BT	Model	Stonic 1.0 T-GDi 74 kW ActieAuto 5d DynamicLine AP	Maintenance mileage	-
Registration date	04/07/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	70 948 km	Engine size	998	interior Color	Orange
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 205/55/17 Summer 6.0 mm



Pirelli 205/55/17 Summer 6.0 mm



Pirelli 205/55/17 Summer 5.5 mm

Pirelli 205/55/17 Summer 5.5 mm

Exterior

2



Part	Step plate
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

3



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



Part	Door
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

9



Part	Step plate
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

11



Part	Door
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

12



Part	Wing moulding
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Replace

13



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

14



Part	Fog light trim
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Replace

15



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

16



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part

Interior cleaning

Position

Front

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

●

●

●

5



Part

Interior tailgate lining

Position

Up

Damages

Scratched

Severity

-

Repair mode

Replace

●

●

●

●

6



Part

Boot carpet

Position

Back left

Damages

Scratched

Severity

-

Repair mode

Replace

●

●

7



Part

Boot carpet

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Replace

●

●

●

8		Part	Boot carpet
		Position	Down
		Damages	Scratched
		Severity	-
		Repair mode	Replace
10		Part	Interior cleaning
		Position	Back
		Damages	Stained/dirty
		Severity	-
		Repair mode	Cleaning