

### Vehicle details

VIN	KNADA817A N6582163	Brand	KIA	Maintenance date	-
Licence Plate	N3-96-BG	Model	Stonic 1.0 T-GDi MHEV 74 kW ComfortLine 5d	Maintenance mileage	-
Registration date	10/09/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	36 373 km	Engine size	998	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

### Inspection Details

Inspection date	07/04/2026	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



### Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓


### Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

### Technical Document




User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

### Tyres




### Exterior

2		Part	Dashboard and drawer	3		Part	Exterior door mirror shell
		Position	-			Position	Left
		Damages	Scratched			Damages	Chemical deposit
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Lumpsum repair

<p><b>4</b></p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dent &amp; Chips</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dent & Chips	Severity	Diameter (mm) > 20	Repair mode	Repair	<p><b>5</b></p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Roof	Position	-	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Wing																						
Position	Back right																						
Damages	Dent & Chips																						
Severity	Diameter (mm) > 20																						
Repair mode	Repair																						
Part	Roof																						
Position	-																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
<p><b>6</b></p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Step plate</td></tr> <tr><td>Position</td><td>Left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Step plate	Position	Left	Damages	Scratched	Severity	-	Repair mode	For info												
Part	Step plate																						
Position	Left																						
Damages	Scratched																						
Severity	-																						
Repair mode	For info																						

**Interior damage**

<p><b>1</b></p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	-	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning										
Position	-										
Damages	Stained/dirty										
Severity	-										
Repair mode	Cleaning										