

# KIA CARENS Carens 2.0 CRDI EX Major A (6pl)



VIN NO KNEFC524335265434 Registration Number GL055YL

MOT Date

Number of Owners

Number of Keys

**Odometer Reading** 

₩-

**:2:** -

**P**1

**172000 km** 

Last Service

Last Service Mileage

First Registration Date

Country First Registered

**=** 

**2** 

2004-05-18

8-

## **Inspection Report Summary**

Customer	BCAuto Encheres	Report Number	P20250903080025
Inspection Date / Place	2025-09-03 / BCA SOLOGNE	Cosmetic Grade	1

### Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Blue	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	6
Charging Cables		NEDC CO2 Rating (q/km)	205

### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			
























## Equipment

Central locking Front fog lamps Roof rails Alloys wheels


Power assisted steering

# **Equipment Details**

Seat Heating No Air Conditioning Yes

Sunroof Type Tilt/Slide Glass

## Cosmetic Damage



	Component	Damage	Comments
1	Floor Carpet	Interior / Dirty	
2	Seat / Back Left	Interior / Dirty	
3	Trunk Carpet	Interior / Dirty	
4	Sunroof	Paint / Corrosion	
5	Shield / Front	Paint / Scratch / Line	
6	Shield / Front	Paint / Chemical Damage	
7	Shield / Back	Paint / Chemical Damage	
8	Fender / Back Left	Paint / Scratch / Line	
9	Door / Back Left	Paint / Scratch / Line	
10	Rim / Back Left	Paint / Chemical Damage	



1. Floor Carpet Interior / Dirty -

2. Seat / Back Left Interior / Dirty -



3. Trunk Carpet Interior / Dirty -

4. Sunroof Paint / Corrosion -



5. Shield / Front Paint / Scratch / Line -

6. Shield / Front Paint / Chemical Damage -



7. Shield / Back Paint / Chemical Damage -

8. Fender / Back Left Paint / Scratch / Line -



9. Door / Back Left Paint / Scratch / Line -

10. Rim / Back Left Paint / Chemical Damage -

#### **Mechanical Condition**

### Tyres

Presence Anti-Theft Lock Nut



- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

#### **Disclaimer Section**

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.