


Vehicle details

VIN	LPSVSEDEE ML016923	Brand	Polestar	Maintenance date	-
Licence Plate	K6-58-JP	Model	2 Pilot Plus	Maintenance mileage	-
Registration date	28/12/2020	Year	2020	Exterior Color	Blue Solid
Odometer	106 691 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	23/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Central locking	✓
Electric windows	✓
4x4	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 245/40/20 Summer 6.0 mm



Pirelli 245/40/20 Summer 6.0 mm



Pirelli 245/40/20 Summer 7.0 mm

Pirelli 245/40/20 Summer 7.0 mm

Exterior

1



Part	Alloy wheel 20"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

2



Part	Door
Position	Front
Damages	Dented
Severity	-
Repair mode	Repair

3



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Alloy wheel 20"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7



Part	Tailgate / Boot door
Position	-
Damages	Hail damaged
Severity	-
Repair mode	Repair

8



Part	Bonnet
Position	-
Damages	Hail damaged
Severity	-
Repair mode	Repair

9



Part	Rear windscreen trim
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

10



Part	Bumper
Position	Front
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

4



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Smart Repair

5



Part	Boot carpet
Position	Down
Damages	Scratched
Severity	-
Repair mode	Smart Repair