


DEKRA Automotive Solutions

Vehicle details

VIN	LPSVSEDEE ML024791	Brand	Polestar	Maintenance date	-
Licence Plate	SFD37Z	Model	Polestar-2-2020	Maintenance mileage	-
Registration date	28/06/2021	Year	2021	Exterior Color	Other
Odometer	141 766 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	1		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Panoramic roof	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Rear parcel shelf	✓
Towing hook	✓

Technical Document

Key	✓
Remote key	✓
Charging kit	✓
Service manual holder	✗
User manual	✗
Warranty booklet	✗
Spare key	✗

DEKRA Automotive Solutions

Tyres

Michelin 245/45/19 T Summer 6.0 mm		Michelin 245/45/19 T Summer 6.0 mm	
Michelin 245/45/19 T Summer 6.0 mm		Michelin 245/45/19 T Summer 6.0 mm	

Winter kit

Nokian 245/45/19 T Winter 7.0 mm		Nokian 245/45/19 T Winter 7.0 mm	
Nokian 245/45/19 T Winter 7.0 mm		Nokian 245/45/19 T Winter 7.0 mm	

Damages

1



Part	Service manual holder
Position	-
Damages	Missing
Severity	-
Repair mode	For info

2



Part	User manual
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

3




Part	Warranty booklet
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

4



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

5



Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

6



Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

7



Part	Aftermarket wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

8



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Lumpsum Paintworks

9



Part	Registration plates
Position	Front
Damages	Dented
Severity	-
Repair mode	Lumpsum replacement

10



Part	Alloy wheel
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

DEKRA Automotive Solutions

11



Part

Bumper

Position

Back

Damages

Scratched

Severity

-

Repair mode

For info

12



Part

Tyre

Position

Back left

Damages

Cut

Severity

-

Repair mode

Lumpsum replacement

13



Part

Door sill

Position

-

Damages

Dented

Severity

-

Repair mode

For info

14



Part

Door sill

Position

Front left

Damages

Dented

Severity

-

Repair mode

Smart Repair

15



Part

Alloy wheel

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum replacement

16



Part

Door

Position

Back left

Damages

Dented

Severity

-

Repair mode

For info

17



Part

Complete service track record

Position

-

Damages

Missing

Severity

-

Repair mode

Lumpsum