


**Vehicle details**

VIN	LPSVSEDEE NL055240	Brand	Polestar	Maintenance date	-
Licence Plate	N7-77-SZ	Model	Polestar 2 78kWh Dual Motor Long Range 5d incl Plu	Maintenance mileage	-
Registration date	29/12/2021	Year	2021	Exterior Color	Black Metallic
Odometer	119 247 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

**Inspection Details**

Inspection date	07/04/2026	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment	
Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
4x4	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element	
Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document	
User manual	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

### Tyres









Continental 245/40/20 Summer 3.0 mm

Continental 245/40/20 Summer 3.0 mm


Continental 245/40/20 Summer 5.0 mm

Continental 245/40/20 Summer 5.0 mm

### Exterior

1		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Repair	2		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Scratched	Severity	-	Repair mode	Repair
	Part	Door																							
Position	Front left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Repair																								
Part	Door																								
Position	Back left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Repair																								
3		<table border="1"> <tr><td>Part</td><td>Alloy wheel 20"</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 20"	Position	Back left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	4		<table border="1"> <tr><td>Part</td><td>Alloy wheel 20"</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 20"	Position	Back right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Alloy wheel 20"																								
Position	Back left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Alloy wheel 20"																								
Position	Back right																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								
5		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dent &amp; Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Dent & Chips	Severity	-	Repair mode	Repair	6		<table border="1"> <tr><td>Part</td><td>Alloy wheel 20"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 20"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Door																								
Position	Back right																								
Damages	Dent & Chips																								
Severity	-																								
Repair mode	Repair																								
Part	Alloy wheel 20"																								
Position	Front right																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								

### Others

7		Part	Damage appraisal
		Position	-
		Damages	Stone impact
		Severity	-
		Repair mode	For info