

Inspection Protocol



TESLA MODEL 3 LONG RANGE AWD, 440HK, 2023

Vehicle information

License plate	KNJ63X	Inspected by	T.H.
Year model	2023	Date of inspection	2025-03-13
Manuf. year/month	2023-03	City	Björkvik
First day in traffic	2023-04	Keys	2
Colour	Grå	Service book	Elektronisk servicebok
Mileage	30 400 km	Latest service	-
Fuel	EI (EV)	Mileage at the latest service	-
Transmission	Automat	Summer tires	18" alu-fälg 4/4/5/5
Engine effect	324 kW	Winter tires	alu-fälg odubbat 5/5/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Summer	Rim damage 2 wheel		220 €
Door, Rear left	Scratches below 30 mm		60 €
Bumper, Rear	Repor, 3-10 cm		80 €
Door, Front right	Dings		-
Bumper, Front	Wide scratch		240 €
Bonnet	Chips, several		160 €

Total excl. VAT	760 €
-----------------	-------

Images



[See all images in large format](#)





















Fälgar & Däck Sommar Fälgskada 2 hjul 3 000 kr



Dörr Vänster bak Repor under 3 cm 800 kr



Stötfångare Bak Repor, 3-10 cm 1 100 kr



Dörr Höger fram Dörruppslag



Stötfångare Fram Skrap 3 300 kr



Motorhuv Stenskott flertal 2 200 kr

