



Tesla 3 (KKL): 2BPZ302

Vinnumber:	LRW3E7EK9NC482455	Versionname:	Model 3 Long-Range Dual Motor AWD 476pk/cv 4p
First Registrationdate:	10/02/2022	Fiscalpower:	
Expertise Mileage:	53572	Power Kw:	69
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	Geen melding		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	Tow bar removable
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/45/18/98 V			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				6.0
Tyre size FL				235/45 R 18 98 V
Tyre size FR				235/45 R 18 98 V
Tyre size RL				235/45 R 18 98 V
Tyre size RR				235/45 R 18 98 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Data erasure, Maintenance, Check

No pictures to display

Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)

