



TESLA MODEL 3: GJ-246-HB

Vinnnumber:	LRW3E7EL5NC617911	Versionname:	
First Registrationdate:	7/09/2022	Fiscalpower:	
Expertise Mileage:	72759	Power Kw:	
Bodytype:	Berline	Body colour:	Red
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Electric	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Rear view camera
Number keys remote	2	
GPS big screen color		

Tyres

235/35/20/92 Y				
Summer tyres:	Fr.L.	Pirelli: 80%	Fr.R.	Pirelli: 85%
	Re.L.	Pirelli: 85%	Re.R.	Pirelli: 80%
Tyre profile depth FL				2.9
Tyre profile depth FR				2.6
Tyre profile depth RL				2.6
Tyre profile depth RR				2.9
Tyre size FL				235/35 R 20 92 Y
Tyre size FR				235/35 R 20 92 Y
Tyre size RL				235/35 R 20 92 Y
Tyre size RR				235/35 R 20 92 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Tyres, No damage, Acceptable



Tyre FR, Out of tolerance, Replace




Tyre RR, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door RL, Dent(s), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Boot lid covering R, Scratch(es), Smart repair

