


Vehicle details

VIN	LRW3E7FS9 PC771840	Brand	TESLA	Maintenance date	-
Licence Plate	S1-73-TN	Model	Model 3 RWD 4d	Maintenance mileage	-
Registration date	17/04/2023	Year	2023	Exterior Color	Black Solid
Odometer	242 251 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	15/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Wireless charger	✗
Vehicle charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Card Key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 235/40/19 Summer 4.0 mm









Pirelli 235/40/19 Summer 4.0 mm



Pirelli 235/40/19 Summer 2.0 mm

Pirelli 235/40/19 Summer 2.0 mm

Exterior

1		Part Position Damages Severity Repair mode	Wing Front left Dented Diameter (mm) > 20 Smart Repair	2		Part Position Damages Severity Repair mode	Alloy wheel 19" Front left Scratched - Lumpsum repair
3		Part Position Damages Severity Repair mode	Wing Back left Scratched Length (cm) > 10 Repair	4		Part Position Damages Severity Repair mode	Alloy wheel 19" Back left Scratched - Lumpsum repair
5		Part Position Damages Severity Repair mode	Tailgate / Boot door - Misaligned - Adjust	6		Part Position Damages Severity Repair mode	Bumper Back Broken - Replace
7		Part Position Damages Severity Repair mode	Alloy wheel 19" Back right Scratched - Lumpsum repair	8		Part Position Damages Severity Repair mode	Wing Back right Dent & Chips Diameter (mm) > 20 Repair
9		Part Position Damages Severity Repair mode	Door Back right Scratched Length (cm) > 10 Repair	10		Part Position Damages Severity Repair mode	Sill Right Scratched Length (cm) > 10 Repair
11		Part Position Damages Severity Repair mode	Alloy wheel 19" Front right Scratched - Lumpsum repair	12		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair
13		Part Position Damages Severity Repair mode	Windscreen - Stone impact - For info	15		Part Position Damages Severity Repair mode	Reflector Back left Broken - Replace

Others

14



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info