

Inspection Protocol



TESLA MODEL Y LONG RANGE AWD

Vehicle information

License plate	BXK63P	Inspected by	A.H.
Year model	2021	Date of inspection	2025-03-13
Manuf. year/month	2021-10	City	Falkenberg
First day in traffic	2021-11	Keys	-
Colour	Svart	Service book	
Mileage	-	Latest service	-
Fuel	El (EV)	Mileage at the latest service	-
Transmission	Automat	Summer tires	20" alu-fälg 2/3/4/4
Engine effect	378 kW	Winter tires	alu-fälg odubbat 6/6/7/7

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Summer	1 tire below 3 mm		110 €
Rims & Tires, Summer	Rim damage 2 wheel		220 €
Wing, Front left	Paint retouch traces		0 €
Door, Front left	Scratches below 30 mm		60 €
Door, Front right	Dings		-
Door, Front right	Other	Passagerarens rutan djup reva	-
Wing, Front right	Paint retouch traces		0 €
Bumper, Front	Chips, several		60 €
Bonnet	Chip		60 €
Glass, Windshield	Chip		20 €
Rims & Tires, Winter	Rim damage 1 wheel	Hf	110 €

Total excl. VAT	640 €
-----------------	-------

Images

[See all images in large format](#)

























