



TESLA MODEL Y

MODEL Y Grande Autonomie Dual Motor AWD

VIN NO LRWYGCEK7PC809527
Registration Number GN471SM



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2023-05-02

Odometer Reading



30474 km

Country First Registered



Inspection Report Summary


Customer	BCAuto Encheres	Report Number	P20250519095621
Inspection Date / Place	2025-05-19 / BCA MITRY	Cosmetic Grade	1



Vehicle Summary



Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Battery Electric Vehicle	Gearbox Type	CVT (constantly varying transmission)
Colour	Grey	Engine Size (cc)	
Engine Size		No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	
Battery State of Health	95		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warranty			







Equipment

Central locking	Electrically folding wing mirrors	Rear parking sensors	Electric Tailgate
Cruise control	Front parking sensors	Satellite navigation	Electrically adjustable seats
Radio	Alloys wheels	Stability control	Front fog lamps

Power assisted steering

Equipment Details

Seat Heating	Front	Air Conditioning	Yes
Sunroof Type	Fixed Panoramic		


Wheels & Tyres

Left Rear Tyre Depth	5	Left Front Tyre Depth	5
Right Front Tyre Depth	5	Right Rear Tyre Depth	5

Cosmetic Damage

11 Dommages

0 Dommages




Component		Damage	Comments
1	Door / Back Left	Paint / Scratch / Line	
2	Rim / Back Left	Out of Bodywork / Scratch	
3	Side Panel / Back Left	Paint / Scratch / Line	
4	Door / Front Left	Paint / Scratch / Line	
5	Rim / Front Left	Out of Bodywork / Scratch	
6	Bumper / Front	Paint / Scratch / Line	
7	Rim / Front Right	Out of Bodywork / Scratch	
8	Door / Front Right	Paint / Scratch / Line	
9	Door / Back Right	Paint / Scratch / Line	
10	Rim / Back Right	Out of Bodywork / Scratch	
11	Tailgate	Paint / Scratch / Line	




1. Door / Back Left
Paint / Scratch / Line -



2. Rim / Back Left
Out of Bodywork / Scratch -



3. Side Panel / Back Left
Paint / Scratch / Line -



4. Door / Front Left
Paint / Scratch / Line -



5. Rim / Front Left
Out of Bodywork / Scratch -



6. Bumper / Front
Paint / Scratch / Line -



7. Rim / Front Right
Out of Bodywork / Scratch -



8. Door / Front Right
Paint / Scratch / Line -



9. Door / Back Right
Paint / Scratch / Line -



10. Rim / Back Right
Out of Bodywork / Scratch -



11. Tailgate
Paint / Scratch / Line -

Levels			
Level - Oil	Not available	Coolant Fluid - Condition	NA
Oil - Condition	NA	Coolant Fluid	NA
Brakes Fluid	NA		
Engine			
Cross Member	✓	Serpentine Belt	NA
Control Liquid Leak	NA		
Equipments Test			
Dump / Trail / Tail Gate Lift	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA
Central Locking	✓	Audio Equipment	✓
Navigation System	✓	AC / Heating System	✓
Parking Sensors / Cameras Functioning	✓		
Tyres			
Presence Anti-Theft Lock Nut	✓		
Dashboard Lights			
ABS Warning Light	✓	Diesel Particulate Filter Light	NA
ESP Fault/Traction Control Malfunction Light	NA	4WD Light	✓
Dashboard Working	✓	Engine Light	✓
Oil Pressure Warning Light	!	Airbag Warning Light	✓
Brake Warning Light	✓	Level - Fuel / Battery	39
Transmission Warning Light	✓	Service Light	✓
Steering Fluid Level	NA		
Hybrid/EV			
Charge Port Condition	!	Charge lead 1 condition /Charge lead 2 condition	✓
Hybrid System Fault	✓		

Test Drive Inspection

Test Drive			
Engine functioning	NA	Engine / Aux Belt / Pulley Noise	NA
Vehicle Starts	✓	Steering Noise/Gripping	NA
Engine Power	NA	Smoke Quantity	NA
Transmission	NA	Clutch Functioning	NA
Brakes Functionning	✓	Steering	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.