



Tesla Model Y: 2BJT664

Vinnumber:	LRWYGCEK9MC139149	Versionname:	
First Registrationdate:	10/12/2021	Fiscalpower:	
Expertise Mileage:	110356	Power Kw:	158
Bodytype:		Parking lot	2303
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Grey
Fueltype:	Electric		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Home (BE)	No		
Registration Certificate Car (BE)	Yes		

Options

Radio multimedia		Seats electric F R	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Seats electric F L	
Type of GPS	GPS big screen color	Front parking sensors	
Cruise Control		Panoramic roof	
Type of climate control	Autom climate control	Type of Tow bar	Tow bar removable
Number of keys total	2		
Type of headlighting	Headlighting LED		
Type of Lining	Lining leather		

Limited Technical Inspection

Tyres

Tyre size RL	255/40 R 20 101 V
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	5.0
Tyre profile depth RR	5.0
Tyre make FR	264
Tyre size FR	255/40 R 20 101 V
Tyre make RR	264
Tyre size RR	255/40 R 20 101 V

255/40/20/101 V				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Tyre profile depth FL	5.0
Tyre make FL	264
Tyre size FL	255/40 R 20 101 V
Tyre type FR	Summer
Tyre profile depth RL	5.0
Tyre type RR	Summer
Tyre make RL	264

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Total cost ex VAT	1983,57
Interior, Worn, Acceptable	0,00



Bonnet, Chemical polution, Repair and paint (complete) 475,09



Alloy rim RL, Scratch(es), Repair and paint (complete) 129,66



Wing RL, Dent(s), Paintless dent repair 93,06



Door RL, Scratch(es), Polish 0,00



Door FL, Scratch(es), Polish 0,00



Wing FL, Scratch(es), Polish 0,00



Wing FL, Scratch(es), Repair and paint (complete) 360,60



Internal boot lining R, Scratch(es), Smart repair 113,74



Tailgate / Boot, Dent(s), Repair and paint (complete) 552,10



Alloy rim RR, Scratch(es), Repair and paint (complete) 129,66



Door RR, Scratch(es), Polish 0,00



Door FR, Scratch(es), Acceptable 0,00



Wing FR, Scratch(es), Polish 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 129,66

