



## MG ZS: G961XB

|                         |                          |                         |  |
|-------------------------|--------------------------|-------------------------|--|
| Vinnnummer:             | <b>LSJW74094LZ022366</b> | Versionname:            | <b>ZS-e 105kW/ 44,5kWh Luxury (SAIC)</b> |
| First Registrationdate: | <b>31/12/2019</b>        | Fiscalpower:            |  |
| Expertise Mileage:      | <b>90933</b>             | Power Kw:               | <b>105</b>                               |
| Bodytype:               |                          | Body colour:            | <b>Pebble Black metallic</b>             |
| Gearbox:                | <b>Automatic</b>         | Paint type:             | <b>Metalic</b>                           |
| Transmission:           | <b>Front</b>             | Type of rims (mounted): | <b>Aluminium</b>                         |
| Fueltype:               | <b>Electric</b>          | Parking lot:            | <b>817</b>                               |
| Number of seats:        | <b>5</b>                 |                         |  |
| Type of rims (mounted): | <b>Aluminium</b>         |                         |  |
| Maintenance needed:     | <b>No</b>                |                         |  |

## Options

|                        |          |                      |  |
|------------------------|----------|----------------------|--|
| Number of keys total   | <b>2</b> | Telephone equipment  |  |
| Number keys remote     | <b>2</b> | Lining leather       |  |
| GPS                    |          | Sun Roof electric    |  |
| Manual climate control |          | Panoramic roof       |  |
| Windows electric F     |          | Central consol F     |  |
| Radio multimedia       |          | Luggage cover        |  |
|                        |          | Rear parking sensors |  |

## Degree of wear

| 215/50/17/96 V        |       |                  |       |                  |
|-----------------------|-------|------------------|-------|------------------|
| Winter tyres:         | Fr.L. | Goodyear: 5,1 mm | Fr.R. | Goodyear: 6 mm   |
|                       | Re.L. | Goodyear: 6,4 mm | Re.R. | Goodyear: 5,9 mm |
| Tyre profile depth FL |       |                  |       | 5.1              |
| Tyre profile depth FR |       |                  |       | 6.0              |
| Tyre profile depth RL |       |                  |       | 6.4              |
| Tyre profile depth RR |       |                  |       | 5.9              |
| Tyre size FL          |       |                  |       | 215/50 R 17 96 V |
| Tyre size FR          |       |                  |       | 215/50 R 17 96 V |
| Tyre size RL          |       |                  |       | 215/50 R 17 96 V |
| Tyre size RR          |       |                  |       | 215/50 R 17 96 V |
| Tyre type FL          |       |                  |       | Winter           |
| Tyre type FR          |       |                  |       | Winter           |
| Tyre type RL          |       |                  |       | Winter           |
| Tyre type RR          |       |                  |       | Winter           |
| Tyre make FL          |       |                  |       | 259              |
| Tyre make FR          |       |                  |       | 259              |
| Tyre make RL          |       |                  |       | 259              |
| Tyre make RR          |       |                  |       | 259              |

## Assistance equipment

|  |          |
|--|----------|
| Number of charging cables (normal)       | <b>1</b> |
| Number of charging cables (rapid charge) | <b>1</b> |

Door FL, Scratch(es), Repair and paint (complete)





Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper trim F, Scratch(es), Replace



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Polish



Wing RR, Scratch(es), Repair and paint (complete)



Wheel arch cover RR, Scratch(es), Replace



Roof pillar R, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Polish

