



VOLVO XC60: FR-603-EY

Vinnnumber:	LYVUZBMUDLB567138	Versionname:	
First Registrationdate:	7/07/2020	Fiscalpower:	
Expertise Mileage:	49192	Power Kw:	
Bodytype:	SUV	Body colour:	Dark Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4x4	Interior colour:	Dark Brown
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Tow bar
Number keys remote	2	Sun Roof electric
GPS big screen color		Luggage cover
		Rear view camera

Degree of wear

255/45/20/105 Y				
Summer tyres:	Fr.L.	Uniroyal: 0%	Fr.R.	Uniroyal: 0%
	Re.L.	Uniroyal: 0%	Re.R.	Uniroyal: 0%
Tyre profile depth FL				8.1
Tyre profile depth FR				8.2
Tyre profile depth RL				8.1
Tyre profile depth RR				8.1
Tyre size FL				255/45 R 20 105 Y
Tyre size FR				255/45 R 20 105 Y
Tyre size RL				255/45 R 20 105 Y
Tyre size RR				255/45 R 20 105 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	0		

Backrest cover FL, Scratch(es), Repair/replace (lump sum)



Seat cover RL, Scratch(es), Repair/replace (lump sum)



Backrest cover RL, Scratch(es), Repair/replace (lump sum)



Tyres, No damage, Acceptable



Alloy rim FL bitone/polychrome, Bad repair, Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Bad repair, Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Bad repair, Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Replace





Door seal R, Unclasp, Dismount/Mount

