



Volvo XC60: K204JP

Vinnumber:	LYVUZBMVDLB518319	Versionname:	XC60 T8 Twin Engine 287kW 4WD Momentum Pro aut
First Registrationdate:	12/01/2021	Fiscalpower:	
Expertise Mileage:	151941	Power Kw:	223
Bodytype:		Paint type	Metallic
Gearbox:	Automatic	Body colour	Onyx Black metallic
Transmission:	4 Wheel-drive	Parking lot	1019
Fueltype:	Hybrid Petrol	Type of rims (mounted)	Aluminium
Number of seats	5		
Maintenance needed	Yes		
Type of rims (mounted)	Aluminium		

Options

GPS	Rear parking sensors
Number of keys total	2 Hook
Windows electric F	Central consol F
Radio multimedia	Headlights Xenon/LED/Laser
Autom climate control	Front parking sensors
	Panoramic roof
	Luggage cover
	Telephone equipment
	Lining leather
	Sun Roof electric

Degree of wear

Tyre profile depth RR				4.2
Tyre size FR				235/60 R 18 107 V
Summer tyres:	235/60/18/107 V			
	Fr.L.	Michelin: 6,9 mm	Fr.R.	Michelin: 6,7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4,2 mm
Tyre size RR				235/60 R 18 107 V
Tyre make RR				261
Tyre profile depth FL				6.9
Tyre type FR				Summer
Tyre size FL				235/60 R 18 107 V
Tyre make FL				261
Tyre profile depth RL				4.0
Tyre type RR				Summer
Tyre make RL				261
Tyre size RL				235/60 R 18 107 V
Tyre type FL				Summer
Tyre type RL				Summer
Tyre profile depth FR				6.7
Tyre make FR				261

Assistance equipment

Number of charging cables (rapid charge)	1
Number of charging cables (normal)	0

Service, Maintenance, Execute



Interior, Stain, Cleaning



Door RL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Roof pillar L, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper FM, Scratch(es), Repair and paint (complete)




LED headlight L, Scratch(es), Repair



Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)





Roof pillar R, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Rear light L, Scratch(es), Replace

