



HYUNDAI i10

i10 1.1

VIN NO MALAM51BAAM716525

Registration Number BAAM716525



MOT Date

2026-10-01

Last Service

-

Number of Owners

1

Last Service Mileage

-

Number of Keys

2

First Registration Date

2011-05-10

Odometer Reading

94075 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251006131057
Inspection Date / Place	2025-10-06 / SULOJA Brackel	Cosmetic Grade	4


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	1086
Engine Size	1.1	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	119
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	Anti-lock braking	Stability control	Central locking
Airbag Status	Auxiliary Socket	CD Player	Radio

Equipment Details


Tow Ball Type	Detachable	Air Conditioning	No
---------------	------------	------------------	----

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

11 Schäden



3 Schäden



Component		Damage	Comments
1	Seat Cushion / Front Left	Interior / Ripped	
2	Panel Filling / Back Left	Interior / Holed	
3	Panel Filling / Front Right	Interior / Scratched	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Hood	Bodywork / Dent / Dent	
6	Door / Front Left	Paint / Scratch / Scuff	
7	Door / Back Left	Bodywork / Dent / Dent	
8	Roof	Bodywork / Dent / Hail Area	
9	Side Panel / Back Left	Bodywork / Dent / Dent	
10	Side Panel / Back Right	Paint / Scratch / Scuff	
11	Door / Back Right	Paint / Scratch / Scuff	
12	Door / Front Right	Paint / Scratch / Scuff	

13	Rocker Panel / Center Right	Paint / Scratch / Scuff
----	-----------------------------	-------------------------

14	Door / Front Left	Paint / Scratch / Scuff
----	-------------------	-------------------------



1. Seat Cushion / Front Left
Interior / Ripped -




2. Panel Filling / Back Left
Interior / Holed -



3. Panel Filling / Front Right
Interior / Scratched -




4. Bumper / Front
Paint / Scratch / Scuff -




5. Hood
Bodywork / Dent / Dent -




6. Door / Front Left
Paint / Scratch / Scuff -




7. Door / Back Left
Bodywork / Dent / Dent -




8. Roof
Bodywork / Dent / Hail Area -



9. Side Panel / Back Left
Bodywork / Dent / Dent -




10. Side Panel / Back Right
Paint / Scratch / Scuff -



11. Door / Back Right
Paint / Scratch / Scuff -



12. Door / Front Right
Paint / Scratch / Scuff -



13. Rocker Panel / Center Right
Paint / Scratch / Scuff -



14. Door / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Equipments Test

Central Locking	✓	Audio Equipment	✓
AC / Heating System	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)