

Vehicle details

VIN	MMCXNA03A MH010217	Brand	MITSUBISHI	Maintenance date	-
Licence Plate	L0-24-HG	Model	SPACE STAR 1.2 Cool+ SDA 5d	Maintenance mileage	-
Registration date	21/05/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	61 943 km	Engine size	1193	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	09/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✗

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓

Tyres

Hankook 165/65/14 Summer 6.5 mm		Hankook 165/65/14 Summer 6.0 mm	
Continental 165/65/14 Summer 7.0 mm		Continental 165/65/14 Summer 7.0 mm	

Exterior

1		Part	Roof	2		Part	Bonnet
		Position	-			Position	-
		Damages	Dented			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Smart Repair

3



Part

Bumper

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

4



Part

Door

Position

Front right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

5



Part

Door

Position

Back right

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

6



Part

Wing

Position

Back right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

7



Part

Bumper

Position

Back

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

8



Part

Wing

Position

Back left

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

9



Part

Door

Position

Back left

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

10



Part

Step plate

Position

Front left

Damages

Dented

Severity

-

Repair mode

For info

●

●

12



Part

Door

Position

Front left

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

Interior damage

11



Part	Rear parcel shelf
Position	-
Damages	Missing
Severity	-
Repair mode	Replace