

Vehicle details

VIN	MMCXNA03A MH011680	Brand	mitsubishi	Maintenance date	-
Licence Plate	L3-04-JX	Model	SPACE STAR 1.2 Cool+ SDA 5d	Maintenance mileage	-
Registration date	03/06/2021	Year	2021	Exterior Color	Silver Metallic
Odometer	89 249 km	Engine size	1193	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Continental 165/65/14 Summer 4.0 mm		Continental 165/65/14 Summer 5.0 mm	
Continental 165/65/14 Summer 5.5 mm		Continental 165/65/14 Summer 5.0 mm	

Exterior

3		Part	Tailgate / Boot door	4		Part	Bumper
		Position	-			Position	Back
5		Damages	Scratched	6		Damages	Dent & Chips
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair
						Part	Roof
		Position	Back right			Position	-
		Damages	Dented			Damages	Dent & Chips
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair

7



●

●

●

●

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

8



●

●

●

●

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

9



●

●

●

●

●

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

10



●

●

●

●

●

Part	Door
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

12



●

●

●

Part	Step plate
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

Interior damage

1



Part

Fabric seat

Position

Back

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

2



Part

Fabric seat

Position

Front

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

13



Part

Fabric seat

Position

Front left

Damages

Burnt

Severity

-

Repair mode

Smart Repair

15



Part

Seat back covering

Position

-

Damages

Broken

Severity

-

Repair mode

Replace

11



Part

Fabric seat

Position

Back left

Damages

Burnt

Severity

-

Repair mode

Smart Repair

14



Part

Interior roof lining

Position

Front left

Damages

Burnt

Severity

-

Repair mode

Smart Repair