

Vehicle details

VIN	MMCXNA03A MH014145	Brand	mitsubishi	Maintenance date	-
Licence Plate	L6-31-NP	Model	SPACE STAR 1.2 Cool+ SDA 5d	Maintenance mileage	-
Registration date	26/06/2021	Year	2021	Exterior Color	Silver Metallic
Odometer	113 947 km	Engine size	1193	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	10/09/2025	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Continental 165/65/14 Summer 5.0 mm



Continental 165/65/14 Summer 5.0 mm



Continental 165/65/14 Summer 7.0 mm



Continental 165/65/14 Summer 7.0 mm



Exterior

1		Part	Door	2		Part	Door
		Position	Front left			Position	Back left
3		Damages	Dented	4		Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Smart Repair
		Part	Wing			Part	Wing
		Position	Back left			Position	Back right
		Damages	Dented			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Smart Repair

5



●

●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



●

●

Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



●

●

Part	Wheelcap 14"
Position	Front right
Damages	Missing
Severity	-
Repair mode	For info

8



●

●

●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair