

Vehicle details

VIN	MMCXNA03A MH015980	Brand	mitsubishi	Maintenance date	-
Licence Plate	L6-36-NP	Model	SPACE STAR 1.2 Cool+ SDA 5d	Maintenance mileage	-
Registration date	26/06/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	105 733 km	Engine size	1193	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	08/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✗

Tyres

Nexen 165/65/14 Summer 6.0 mm		Nexen 165/65/14 Summer 6.0 mm	
Nexen 165/65/14 Summer 7.0 mm		Nexen 165/65/14 Summer 7.0 mm	

Exterior

2		Part	Roof	3		Part	Bonnet
		Position	-			Position	Front
4		Damages	Dent & Chips	5		Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Smart Repair
						Part	Door
		Position	Front			Position	Front right
		Damages	Scratched			Damages	Dented
		Severity	Length (cm) > 10			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Smart Repair

6



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



Part	Wing
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

8



Part	Bumper
Position	Back
Damages	Broken
Severity	Length (cm) > 10
Repair mode	Repair

9



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

10



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace