

Vehicle details

VIN	MMCXNA03A MH021458	Brand	mitsubishi	Maintenance date	-
Licence Plate	L8-39-KB	Model	SPACE STAR 1.2 Cool+ SDA 5d	Maintenance mileage	-
Registration date	05/06/2021	Year	2021	Exterior Color	Silver Metallic
Odometer	87 755 km	Engine size	1193	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	07/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Goodyear 185/65/14 Summer 5.0 mm		Goodyear 185/65/14 Summer 5.0 mm	
Bridgestone 185/65/14 Summer 1.5 mm		Bridgestone 185/65/14 Summer 1.5 mm	

Exterior

2		Part	Wing	3		Part	Door
		Position	Front left			Position	Front left
4		Damages	Dented	5		Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Repair
						Part	Bumper
						Position	Back
						Damages	Dent & Chips
						Severity	-
						Repair mode	Replace

6



●●

Part	Tailgate / Boot door
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7



●●●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

8



●●

Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

9



●●

Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

10



●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

11



●●●●

Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

12



●●●●●●●●

Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

1



Part	Fabric seat
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning