

Vehicle details

VIN	MMCXNA03A NH001715	Brand	MITSUBISHI	Maintenance date	-
Licence Plate	N4-28-FK	Model	SPACE STAR 1.2 Cool+ SDA 5d	Maintenance mileage	-
Registration date	29/09/2021	Year	2021	Exterior Color	Silver Metallic
Odometer	60 446 km	Engine size	1193	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	09/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Remote key	✓
Key	✗

Tyres

Bridgestone 165/65/14 Summer 4.0 mm		Bridgestone 165/65/14 Summer 4.0 mm	
Bridgestone 165/65/14 Summer 4.5 mm		Bridgestone 165/65/14 Summer 4.5 mm	

Exterior

4		Part	Roof	5		Part	Bonnet
		Position	-			Position	-
6		Damages	Chemical deposit	7		Damages	Dented
		Severity	-			Severity	Diameter (mm) > 20
		Repair mode	Lumpsum repair			Repair mode	Smart Repair
		Part	Bumper			Part	Wing
		Position	Front			Position	Front left
		Damages	Scratched			Damages	Dent & Chips
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair

8		PartDoor PositionFront left DamagesDent & Chips Severity- Repair modeRepair	10		PartDoor PositionBack left DamagesDented SeverityNumber > 2 Repair modeSmart Repair
11		PartRoof post A/B/C PositionLeft DamagesDented SeverityNumber > 2 Repair modeSmart Repair	12		PartWing PositionBack left DamagesDent & Chips Severity- Repair modeRepair
13		PartBumper PositionBack DamagesScratched Severity- Repair modeRepair	14		PartWing PositionBack right DamagesDented SeverityNumber > 2 Repair modeSmart Repair
15		PartDoor PositionBack right DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair	16		PartDoor PositionFront right DamagesScratched Severity- Repair modeRepair
17		PartWing PositionFront right DamagesDent & Chips Severity- Repair modeRepair			

Interior damage

1		PartKey Position- DamagesMissing Severity- Repair modeReplace			
2		PartInterior cleaning PositionFront DamagesStained/dirty Severity- Repair modeCleaning	3		PartInterior cleaning PositionBack DamagesStained/dirty Severity- Repair modeCleaning

9



Part	Rear-view mirror base plate interior lining
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Smart Repair